

# Tewantin Moderate Flood Alert Possible Consequence

This information is indicative only and has been derived from design flood estimations.  
The consequences of actual flood events may differ from those listed here.

Type	Primary	Moderate Event Hazard Level	Moderate Hazard Description
Road	Daintree Way	●	Potentially dangerous water levels over road
Road	Frying Pan Track	●	Potentially dangerous water levels over road
Road	Golf Course Drive	●	Potentially dangerous water levels over road
Road	Hilton Esplanade - Boat Ramp + Fire Station	●	Potentially dangerous water levels over road
Road	Lake Entrance Boulevard	●	Potentially dangerous water levels over road
Road	Lake Weyba Drive	●	Potentially dangerous water levels over road
Road	Mill Street	●	Possible water over road
Road	Moorindil Street	●	Possible water over road
Road	Noosa District Sports Complex	●	Potentially dangerous water levels over road
Road	Noosa River Drive	●	Potentially dangerous water levels over road
Road	Noosa Springs Drive	●	Potentially dangerous water levels over road
Road	Seacove Court	●	Potentially dangerous water levels over road
Road	Shorehaven Drive	●	Potentially dangerous water levels over road
Road	Tewantin Ferry	●	Potentially dangerous water levels over road
Commercial	Noosa River Houseboats	●	Water levels nearing business floor level
Road	Boat Ramp - Noosa Wharf	●	Water nearing road surface
Jetty	Noosa Wharf Carpark - Jetty 1	●	Potentially dangerous water levels over road
Jetty	Noosa Wharf Carpark - Jetty 2	●	Potentially dangerous water levels over road
Road	Hilton Esplanade Boat Ramp	●	Possible water over road
Commercial	Noosa River Services	●	Water levels nearing business floor level
Road	Pathway - Noosa Waters Entrance	●	Potentially dangerous water levels over road
Commercial	Noosa Boathouse floating restaurant	●	Water levels nearing business floor level
SewerPump	SewerPump_5-SPS-TWN005 P1	●	Sewer pump station inundated. Beware of overflow contamination.
SewerPump	SewerPump_6-SPS-TWN005 P2	●	Sewer pump station inundated. Beware of overflow contamination.
SewerPump	SewerPump_9-SPS-TWN009 P1	●	Sewer pump station inundated. Beware of overflow contamination.
SewerPump	SewerPump_10-SPS-TWN009 P2	●	Sewer pump station inundated. Beware of overflow contamination.
SewerPump	SewerPump_31-SPS-NVL021 P1	●	Sewer pump station may be inundated
SewerPump	SewerPump_32-SPS-NVL021 P2	●	Sewer pump station may be inundated
Bus Stop	Bus Stop 700503 Hilton Terrace	●	Bus Stop may be isolated