

# Boreen Pt Major Flood Alert Possible Consequences

This information is indicative only and has been derived from design flood estimations.  
The consequences of actual flood events may differ from those listed here.

Type	Primary	Major Event Hazard Level	Major Hazard Description
Road	Boreen Parade	●	Potentially dangerous water levels over road
Road	Boreen Pt Esplanade	●	Potentially dangerous water levels over road
Road	Bundoora Street	●	Potentially dangerous water levels over road
Road	Cootharaba Downs Road - North of Pangola Lane	●	Possible water over road
Road	Cootharaba Downs Road - South of Kamo Lane	●	Potentially dangerous water levels over road
Road	Cootharaba Street	●	Potentially dangerous water levels over road
Road	Duncans Lane	●	Potentially dangerous water levels over road
Road	Hollett Road	●	Potentially dangerous water levels over road
Road	Kamo Lane	●	Possible water over road
Road	Lake Flat Road	●	Potentially dangerous water levels over road
Road	Lake Flat Road - Cnr Woongar St	●	Potentially dangerous water levels over road
Road	Lakeway Drive	●	Potentially dangerous water levels over road
Road	Louis Bazzo Drive - North of Cootharaba Downs Road	●	Potentially dangerous water levels over road
Road	Mary-Anne Drive	●	Potentially dangerous water levels over road
Road	Maximilian Road	●	Potentially dangerous water levels over road
Road	Mckinnon Drive - East of Lake Cooroibah Road	●	Potentially dangerous water levels over road
Road	Urunga Parade	●	Potentially dangerous water levels over road
Road	Woongar Street - Lake Flat Road	●	Potentially dangerous water levels over road
Electrical	Pole mounted substation COOTHARABA DOWNS RD COOTHARABA	●	Electrical substation may to isolated
Electrical	High Voltage Switching Site LOUIS BAZZO DR COOTHARABA	●	Electrical substation likely to be impacted
Electrical	Pole mounted substation LAKE FLAT RD COOTHARABA	●	Electrical substation may to isolated
Electrical	Pole mounted substation KAMO LANE COOTHARABA	●	Electrical substation may to isolated
Electrical	Pole mounted substation TEWAH RD BOREEN POINT	●	Electrical substation may to isolated
SewerPump	Sewer Pump Boreen Parade	●	Sewer pump station may be inundated. Beware of overflow contamination.
SewerPump	Sewer Pump Boreen Parade	●	Sewer pump station may be inundated. Beware of overflow contamination.
SewerPump	Sewer Pump Boreen Pt Esplanade	●	Sewer pump station may be inundated. Beware of overflow contamination.